

FIG. 1




FIG. 2




FIG. 3




FIG. 4

Option 1: Extra Laser, Use of Control Inser For Feedback.




FIGURE 5

Option 2 a & b : Use of Data Laser for Feedback




Figure 6






FIG. 8





FIG. 8



700

FIG. 9




FIG. 10

FIG. 11




FIG. 11

FIG. 12A

To define the problem




FIG. 12A




FIG. 12B




FIG. 13B

860

FIG. 13A

820